

Intermittent Communication Between the TrailerTRACS Transmitter and the Qualcomm Unit

54-279

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD

**Freightliner
Service Bulletin**

General Information

On some Cascadia vehicles, communication can be intermittent between the TrailerTRACS transmitter and the Qualcomm unit. Routing the wiring along the back of the cab will ensure more reliable signal strength.

Use the instructions in this bulletin to modify the TrailerTRACS wiring.

Parts

Refer to [Table 1](#) for parts required for this repair.

| Parts Required | | |
|--------------------|----------------|----------|
| Part | Part Number | Quantity |
| Plug | 23-13142-229 | 1 |
| Connector | PAC 12033731 B | 1 |
| Fuse, ATC, 5-Amp | BUS ATC5 | 1 |
| Terminal MP630P2S | PAC 12020156 L | 4 |
| Terminal GT280S | PAC 15304719 L | 2 |
| 18-Gauge Cable | 48-02493-182 | 20 ft. |
| Wire Crimp, Solder | PHM 1 1861 | 1 |
| Terminal Seal | 23-12497-281 | 1 |

Table 1, Required Parts

Work Instructions

1. Shut down the engine and apply the parking brakes. Chock the tires.
2. Access the driver-side wiring harness.

NOTE: There are three possible installations. On vehicles equipped with a driver-side luggage door, the wiring harness cover is located at the front edge of the luggage compartment. See [Fig. 1](#). On vehicles without a driver-side luggage compartment, the harness is under the side panel located beneath the lower bunk. On daycabs, the harness is located behind the rear upholstery panel.

- On Sleepercabs with a driver-side luggage compartment, open the compartment and remove all stored items. Remove the fasteners from the harness cover, then remove the cover.
 - On Sleepercabs without a driver-side luggage compartment, raise the lower bunk and remove the support panel. Remove the bolt that secures the side panel to the cab floor, then remove the side panel. See [Fig. 2](#).
 - On daycabs, move the driver and passenger seats as far forward and possible. Remove the backwall upholstery panel and the backwall panel. Support the backwall panel with blocks to gain access to the Qualcomm wiring. See [Fig. 3](#).
3. Inspect circuit 45 to make sure that the wiring modification has not already been completed. If the procedure was already performed, circuit 45 will be spliced with an 18-gauge wire and routed as shown in [Fig. 5](#). If the procedure has not been performed, continue with the next step.
 4. Remove the tread plate, kick panel, and lower dash panel from the passenger side of the vehicle. See [Fig. 4](#).

NOTE: See [Fig. 5](#) for the parts required for the wire splice.

Freightliner
Service BulletinFLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 ConventionalCentury Class Conventional
Argosy COE
Cargo
ColumbiaCoronado
Business Class M2
> Cascadia
108SD/114SD

5. Measure and cut enough 18-gauge wire to extend from the driver-side wall under the bunk to the passenger-side wall, and under the passenger-side kick panel to the Qualcomm ECU connector under the dash.
6. Feed the wire through the fuse holder. Strip the wire, then crimp on the fuse holder terminal end.



03/26/2013

f546006

1. Harness Cover

Fig. 1, Driver-Side Luggage Compartment without Auxiliary Heater Option (Sleepercab)

04/02/2013

f546008

1. Side Panel

Fig. 2, Under Bunk Side Panel Removal

7. Cut a 4 to 6 inch (10 to 15 cm) strand of wire.
8. Feed the short strand of wire through the fuse holder. Strip the wire on both ends, then crimp on the fuse holder terminal end.
9. Inside the cab, cut and strip the circuit 45 blue wire.
10. Splice the new wire into circuit 45. See [Fig. 6](#).
 - 10.1 Slide a butt connector onto the the end of circuit 45 that leads to the SAM Chassis.
 - 10.2 Slide the new wire and the other end of circuit 45 into the opposite end of the butt connector.
 - 10.3 Crimp each end of the butt using a crimp tool to secure the wires. See [Fig. 7](#).
 - 10.4 Pull test the wires by hand to ensure the crimp is mechanically solid.
 - 10.5 Heat the splice using a heat gun rated at 1,000°F (538°C) until the sleeve has completely shrunk against the wire and the solder inside the butt connector flows.

Intermittent Communication Between the TrailerTRACS Transmitter and the Qualcomm Unit

54-279

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD

Freightliner
Service Bulletin




Fig. 3, Support the Cab Backwall with Blocks (daycabs)

11. Route the wire to the Qualcomm ECU.

- 11.1 On Sleeper cabs, route the wire underneath the bunk along the bunk support wall and underneath the floor mat.

On daycabs, route the wire along the cab backwall.

NOTE: On Sleepercabs with a driver-side luggage compartment, the wire needs to be routed along the cab wall, underneath the harness cover.

- 11.2 On Sleepercabs, route the wire behind the passenger side B-pillar panel and under the harness cover using fish tape or a wire guide. See [Fig. 8](#).

On daycabs, feed the wire underneath the passenger-side harness cover. See [Fig. 9](#).

- 11.3 Strip the wire end and crimp on terminal 23-13212-120 with seal 23-12497-281.





Fig. 4, Passenger-Side Tread Plate and Kick Panel

Freightliner
Service BulletinFLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 ConventionalCentury Class Conventional
Argosy COE
Cargo
ColumbiaCoronado
Business Class M2
> Cascadia
108SD/114SD**Fig. 5, Wiring Modification Parts**

12. Disconnect the 14- or 16-pin Qualcomm ECU connector. It is located on the passenger-side of the vehicle, behind the kick panel. See [Fig. 10](#).
13. Remove wire 376C4 (orange) from the Qualcomm connector. Refer to module 330 for terminal details. Terminate the wire by adding shrink tubing to the end of the wire. Heat the tubing using a heat gun rated at 1,000°F (538°C) until the sleeve has completely shrunk against the wire.
14. Insert the new wire into the Qualcomm connector in the same cavity where wire 376C4 was connected. See [Fig. 11](#).
15. Tape down the new wire along the inner bunk support, along the cab wall and the passenger-side door frame. See [Fig. 12](#).
16. Install the kick panel, tread plate, and lower dash panel on the passenger-side of the vehicle.
17. On Sleepercabs, install the harness cover on the driver side of the vehicle.

Intermittent Communication Between the TrailerTRACS Transmitter and the Qualcomm Unit

54-279

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD

**Freightliner
Service Bulletin**




Fig. 6, Wire Re-Routed to Qualcomm ECU




Fig. 7, Crimp Tool


18. On daycabs, remove the support blocks, then install the backwall panel, and the upholstery panel.

Freightliner Service Bulletin

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD



04/02/2013

f546017

- 1. Passenger Seat
- 2. Harness Cover

- 3. 18-Gauge Wire
- 4. Wire Guide

Fig. 8, Passenger-Side Wire Routing (tread plate removed)

Intermittent Communication Between the TrailerTRACS Transmitter and the Qualcomm Unit

54-279

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD

**Freightliner
Service Bulletin**




Fig. 9, Wire Fed into the Passenger-Side Harness Cover (daycabs)




Fig. 10, Qualcomm Connector

Freightliner Service Bulletin

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD




06/13/2013

f546012

1. New 18-Gauge Wire

Fig. 11, Qualcomm Connector Wire Location



04/02/2013

f546016

- | | |
|--------------------|---------------------|
| 1. Bunk | 4. Floor Insulation |
| 2. Electrical Tape | 5. Floor Mat |
| 3. 18-Gauge Wire | 6. Auxiliary Heater |

Fig. 12, Wire Routing Under Bunk (auxiliary heater installation shown)

Intermittent Communication Between the TrailerTRACS Transmitter and the Qualcomm Unit

54-279

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD

**Freightliner
Service Bulletin**

Warranty

This procedure is warrantable only if the described condition exists and the repair is performed within the applicable base or extended coverage warranty period. If a failure is not found, this procedure is considered preventive and warranty does not apply.

Normal warranty applies. See [Table 2](#) for QuickClaim damage code and labor allowance information. Refer to this service bulletin by number at the beginning of the claim comments. See [Table 3](#) for OWL VMRS codes and labor allowance information. Enter this service bulletin number in the *Service Bulletin #* field.

| QuickClaim Damage Code and Labor Allowance | | | |
|--|-----------|--|-------------|
| Damage Code | SRT Code | Description | Time: Hours |
| 786-000A04600 | 996-0896A | Qualcomm, TrailerTRACS, Inspect and Rewire | 0.8 |
| | 996-0896B | Qualcomm, TrailerTRACS, Inspect | 0.3 |

Table 2, QuickClaim Damage Code and Labor Allowance

| OWL VMRS Codes and Labor Allowance | | | | | |
|------------------------------------|----------------|------------|-----------|--|-------------|
| Primary Failed Part | Component Code | Cause Code | SRT Code | Description | Time: Hours |
| Qualcomm, TrailerTRACS | 051-008-008 | 12 | 996-0896A | Qualcomm, TrailerTRACS, Inspect and Rewire | 0.8 |
| | | 12 | 996-0896B | Qualcomm, TrailerTRACS, Inspect | 0.3 |

Table 3, OWL VMRS Codes and Labor Allowance