

P0095

Fault code description

Intercooler temperature - Data erratic, intermittent or incorrect at ignition on

Possible cause

1. Faulty wiring
2. Faulty connector
3. Faulty sensor
4. Leaks in the air system

Additional information

Sensor value compared to a corrected average engine power up temperature

Set condition of fault code

This diagnostic only runs if the key has been off for at least 3 hours. Two seconds after key-on, the air temperature post intercooler sensor reading is compared to the average of the other temperature sensors. If the difference is greater than 8°C (14°F) then the fault is set.

Reset condition of fault code

Fault is reset when diagnostic is run with fault condition not present.

Key-off for at least 3 hours. Key-on and wait at least 10 seconds before starting. Start engine and idle for 2 minutes.

M028510 - 07/22/2015 18:14:46

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-12-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P0095, Diagnostic information

Technical data

["Sensor, intercooler temperature \(F750\)"](#)

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

["Intercooler temperature sensor \(F750\)"](#)

Block diagram

["PMCI-2"](#)

Step by step troubleshooting



Please perform the troubleshooting steps below by utilising the breakout harness if necessary to check electrical components such as sensors, electrical control units or harnesses. Back probing is not recommended as it could damage the harness. The ignition should always be in the **OFF** position when connecting or disconnecting electrical components to reduce the likelihood of damage to electrical components.



- This troubleshooting tree is based on the assumption that supply power and earth to the PMCI are functioning properly.
- Disconnecting the PMCI connectors during the troubleshooting process will result in multiple errors.
- For specific electrical component information and pin out locations, always refer to the technical data in Rapido.
- It is necessary to exit the '**active errors**' screen in DAVIE and run the diagnostic test again to identify any change in errors.
- Remember that the truck's operational or mechanical issues may be the root cause of both active and inactive codes. Refer to the 'possible causes' section in Rapido.

Step 1

Visual inspection - Visually inspect the associated component connections and wiring for any of the following:

- Loose or broken clamps on the air system
- Dirt or debris build-up (blockage) at the

front of the intercooler

- Moisture or dirt in the connections
- Damage to the wire harness or insulation
- Damaged or disconnected ECU connections
- Battery damage, contacts that are not tight
- Cuts, holes or abrasions in the air piping
- Incorrectly installed sensor

Was there evidence of any of the above?

- **Yes** – Clean, adjust, repair or replace affected components for any issues identified.

Use DAVIE to re-check for the presence of active faults.

If this related fault is no longer active, then this issue has been resolved. If this related fault is still active, continue to step 2.

- **No** – Proceed to step 2.

Step 2

Electrical Checks intercooler temperature sensor (F750) - For all electrical checks and diagrams, refer to the Engine Service Rapido diagram viewer for detailed schematics, connector pin locations and corresponding signal values.

Based on the fault message provided, confirm that the following electrical values are within specified ranges or limits.

1. Check for supply and signal voltages.
2. Check for cable continuity (no open or short circuit).

Are measured electrical values outside of the expected range or limits?

- **Yes** – Make the appropriate repairs or component replacements.

Use DAVIE to re-check for the presence of

active faults.

If this related fault is no longer active, then this issue has been resolved. If this related fault is still active, continue to step 3.

- **No** – Proceed to step 3.

Step 3

Air side pressure test

1. Perform the prescribed test to determine whether there are any leaks in the air system.

Does the test fail to complete or result in a failed state?

- **Yes** – Make the appropriate repairs or component replacements.

Use DAVIE to re-check for the presence of active faults.

If this related fault is no longer active, then this issue has been resolved. If this related fault is still active, continue to step 4.

- **No** – Proceed to step 4.

Step 4

Replace: Intercooler temperature sensor

1. Replace the identified sensor.
2. Use DAVIE to re-check for the presence of active faults.

Is the fault code inactive?

- **Yes** – Issue has been resolved.
- **No** – Proceed to step 5.

Step 5

Contact the Engine Support Center (ESC) for further assistance.

M046268 - 07/22/2015 18:05:46

with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)