

## P0486

### Fault code description

EGR pressure difference - Out of range, At ignition on

### Possible cause

1. Faulty wiring
2. Faulty connector
3. Faulty sensor
4. Exhaust or coolant leaks
5. Damage to air system components

### Additional information

Monitoring the pressure difference between the EGR differential sensor and zero.

### Set condition of fault code

Two seconds after key-on, a snapshot of the venturi delta pressure reading is taken. If the reading is greater than 0.05 bar (0.73 psi) then the fault is set.

### Reset condition of fault code

Fault is reset when diagnostic is run with fault condition not present.

Key-off for at least 15 seconds. Key-on and wait at least 10 seconds before starting. Start engine and idle for 2 minutes.

M028541 - 07/23/2015 03:11:04

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. ( / )

## P0486, Diagnostic information

Technical data

["Sensor, EGR differential pressure \(F751\)"](#)

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

["EGR differential pressure sensor \(F751\)"](#)

Block diagram

["PMCI-2"](#)

### Step by step troubleshooting



Please perform the troubleshooting steps below by utilising the breakout harness if necessary to check electrical components such as sensors, electrical control units or harnesses. Back probing is not recommended as it could damage the harness. The ignition should always be in the **OFF** position when connecting or disconnecting electrical components to reduce the likelihood of damage to electrical components.



- This troubleshooting tree is based on the assumption that supply power and earth to the PMCI are functioning properly.
- Disconnecting the PMCI connectors during the troubleshooting process will result in multiple errors.
- For specific electrical component information and pin out locations, always refer to the technical data in Rapido.
- It is necessary to exit the '**active errors**' screen in DAVIE and run the diagnostic test again to identify any change in errors.
- Remember that the truck's operational or mechanical issues may be the root cause of both active and inactive codes. Refer to the 'possible causes' section in Rapido.

### Step 1

**Visual inspection** - Visually inspect the associated component connections and wiring for any of the following:

- Damaged or loose connectors
- Bent, broken, corroded or loose connector

pins

- Moisture or dirt in the connections
- Damage to the wire harness or insulation
- Low coolant level or leaking coolant
- Damaged or disconnected ECU connections
- Battery damage, contacts that are not tight
- Signs of exhaust or coolant leaks on the EGR
- Broken or missing clamps on any air component part

Was there evidence of any of the above?

- **Yes** – Clean, adjust, repair or replace affected components for any issues identified.

Use DAVIE to re-check for the presence of active faults.

If this related fault is no longer active, then this issue has been resolved. If this related fault is still active, continue to step 2.

- **No** – Proceed to step 2.

## Step 2

**Electrical Checks EGR differential pressure sensor (F751)** - For all electrical checks and diagrams, refer to the Engine Service Rapido diagram viewer for detailed schematics, connector pin locations and corresponding signal values.

Based on the fault message provided, confirm that the following electrical values are within specified ranges or limits.

1. Check for supply and signal voltages.
2. Check for cable continuity (no open or short circuit).

Are measured electrical values outside of the expected range or limits?

- **Yes** – Make the appropriate repairs or component replacements.

Use DAVIE to re-check for the presence of active faults.

If this related fault is no longer active, then this issue has been resolved. If this related fault is still active, continue to step 3.

- **No** – Proceed to step 3.

### Step 3

#### Replace: EGR pressure difference sensor

1. Replace the identified sensor.
2. Use DAVIE to re-check for the presence of active faults.

#### Is the fault code inactive?

- **Yes** – Issue has been resolved.
- **No** – Proceed to step 4.

### Step 4

Contact the Engine Support Center (ESC) for further assistance.

M046364 - 07/22/2015 16:08:18

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. ( / )