U104C

Fault code description

VTG turbo charger actuator - CAN communication error

Possible cause

- Breakdown in communication in the CAN network
- Open circuit, short circuit to earth or short circuit to supply in the CAN network wiring

Additional information

CAN message monitoring

Set condition of fault code

The PMCI-2 detects an invalid message rate to the VTG after key on.

Reset condition of fault code

This fault code will change to inactive immediately after the diagnostic runs and passes.

M027714 - 07/22/2015 15:07:50

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-19-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

U104C, Diagnostic information

Technical data

"CAN connections of PMCI-2 electronic unit (D365)"

"Rotary speed actuator (L037)"

Location of component(s)

"Location information, PMCI-2"

Electrical diagram(s)

"PMCI-2"

Description of component(s)

"Rotary speed actuator (L037)"

Block diagram

<u>"PMCI-2"</u>

Step by step troubleshooting



Please perform the troubleshooting steps below by utilising the breakout harness if necessary to check electrical components such as sensors, electrical control units or harnesses. Back probing is not recommended as it could damage the harness. The ignition should always be in the OFF position when connecting or disconnecting electrical components to reduce the likelihood of damage to electrical components.



- This troubleshooting tree is based on the assumption that supply power and earth to the PMCI are functioning properly.
- Disconnecting the PMCI connectors during the troubleshooting process will result in multiple errors.
- For specific electrical component information and pin out locations, always refer to the technical data in Rapido.
- It is necessary to exit the 'active errors' screen in DAVIE and run the diagnostic test again to identify a change in errors.
- Remember that the truck's operational or mechanical issues may be the root cause of both active and inactive codes. Refer to the 'possible causes' section in Rapido.

Step 1

With DAVIE connected and key ON, reprogram the engine basis software with the most recent PRS file.

Navigate through DAVIE and monitor errors.

If the fault is still active – Proceed to step 2.

If the fault is NO longer active – Proceed to the verification procedure.

Step 2

With key OFF, disconnect the actuator (L037) from the harness and inspect the connectors and harness for:

- 1. Corroded or dirty pins
- 2. Damaged pins
- 3. Pushed back or expanded pins
- 4. Loose connector
- 5. Moisture in or on the connector
- 6. Damage to the connector shell
- 7. Missing or damaged connector seals
- 8. Wire insulation damage

Dirty or damaged pins/connector?

- Yes A dirty or damaged connection has been detected. Clean, repair or replace the damaged connection or harness if possible
 Proceed to the verification procedure listed at the end of this document.
- No Proceed to step 3

Step 3A

With the actuator connector disconnected, turn the key ON. Check the voltage between the power supply terminal and the earth terminal circuit at the connector harness. (Refer to the OEM manual for the system voltage.)

- If the voltage meets the specification Proceed to step 4.
- If the voltage found does not meet the specification – Proceed to step 3B.

Inspect the batteries to verify that they meet specifications.

- Replace batteries as needed Proceed to the verification procedure.
- If battery replacement is not needed Proceed to step 3C.

Step 3C

Verify that power and earth wiring has no damage from controller harness connector to battery/earth. If an issue is found, repair or replace the wiring.

- If issue found and resolved Proceed to the verification procedure.
- If no issue found or fix does NOT resolve issue – Proceed to step 4.

Step 4

Connect the actuator (L037). With key ON, gently bend, twist and pull the connections, and in between connections in the harness to the actuator (L037), to replicate the fault and/or change the fault status.

- If the actuator power resets (audible clicks) or replicates the fault/changes fault status – An intermittent open circuit is detected. Repair or replace the wiring.
 Proceed to the verification procedure.
- If the actuator power does not reset or fault status is unchanged – Proceed to step 5.

Step 5

Check that isolating any component on the same CAN network does not change the fault code status. Is the fault code status changed?

- Yes Solve the fault code for this component first.
- No Proceed to step 6.

Step 6

With key OFF, check the resistance between CAN-H and CAN-L at the actuator connector. Is the resistance within 120 ohms (+/-12 ohms)?

- Yes Proceed to step 7.
- No Contact the Engine Support Center for further instruction on replacement of the turbo actuator.

Step 7

Check the resistance between CAN-H and CAN-L at the actuator connector (engine harness side). Is the resistance 120 ohms (+/-12 ohms)?

- Yes Proceed to step 9.
- No Proceed to step 8.

Step 8

With key OFF, check the resistance between CAN-H and CAN-L at the PMCI-2 ECU. Is the resistance within 120 ohms (+/-12 ohms)?

- Yes Replace harness. Proceed to the verification procedure listed at the end of this document.
- No Contact the Engine Support Center for further instruction on replacement of the PMCI-2 ECU.

Step 9

Check the resistance between actuator supply/earth to CAN-H and CAN-L at the actuator connector. Is the resistance within specifications (> 5000 ohms)?

- Yes Proceed to step 10.
- No Contact the Engine Support Center for further instruction on replacement of the turbo actuator.

Step 10

Contact the Engine Support Center for further instruction.

Verification procedure

With DAVIE connected and key ON, clear the errors. Start the engine and let it idle to verify with DAVIE that the errors do not reoccur.

M046985 - 07/22/2015 17:04:12

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-19-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)