Review

Multiple choice question

Sheet to be completed - 1

Leçon: 2.5.3

QUESTION:

Identify all defective wheels.

ANSWER CHOICE: Only one answer possible Several possible answers **X**

A)



B)



C)



D)



Refer to if wrong answer:



Multiple choice question

Sheet to be completed - 2

Leçon: 2.5.3

QUESTION:

What oil should you use for this hub?



ANSWER CHOICE: Only one possible answer X Several possible answers

A)

B)

C)

D)









Refer to if wrong answer:



True or False

Sheet to be completed - 3

Leçon: 2.5.3

QUESTION:	
It can be very dangerous to drive without oil in the hub	
ANSWER CHOICES:	
TRUE	
FALSE	
TALOL	
Refer to if wrong answer:	



True or False

Sheet to be completed - 4

Leçon: 2.5.3

QUESTION:			
This label is present on one of the wheel valves of your vehicle. You must have a wheel tightening done before you have traveled 80 km or 10 days.			
No. D'UNITÉ	ROUES INSTALLÉES		
DATE	Kms		
	No. D'UNITÉ		
9373	À VÉRIFIER D'ICI CINQ JOURS OU DANS 100 Kms	9373	
ANSWER CHOICES:			
TRUE			
FALSE			
Refer to if wrong answer:			

cբtr

Multiple choice question

Sheet to be completed - 5

C) There is a high oil pressure in the hub.

Refer to if wrong answer:

D) The plastic see-thru part can be easily damaged.

QUESTION:

When adding wheel bearing oil, with this type of hub cap, certain precautions should be taken when removing the red cap, explain why.

ANSWER CHOICE: Only one possible answer X Several possible answers

1. The oil drains completely by removing the cap.

B) This cap is for single use. We cannot put it back.



Multiple choice question

Sheet to be completed - 6

Leçon: 2.5.3

QUESTION: If this label is attached to the yellow brake button of a vehicle. What does it mean? KENWORTH **AVERTISSEMENT / WARNING** Kenworth Montréal Suite au travail effectué sur le véhicule, un torquage (couple de serrage) est nécessaire avant : 100 km. Following the work performed on the vehicle, a wheel re-torque is required before: 100 km. VOTRE RESPONSABILITÉ: ASSUREZ-VOUS QUE LE TORQUAGE SOIT EFFECTUÉ. YOUR RESPONSIBILITY: MAKE SURE THAT THE RE-TORQUE IS PERFORMED. PARKING # Série / Serial # : JDH& J42 Date de réparation / Repair date : OH / 12 | 19 (m: 83292 Couple de serrage: 500 lbs/pi *roue à rayon : 300 lbs/pi Wheel re-torque 500 lbs/pi *spoke wheel: 300 lbs/pi RETIREZ CETTE ÉTIQUETTE UNE FOIS LE COUPLE DE SERRAGE EFFECTUÉ. REMOVE THIS TAG ONCE THE RE-TORQUE HAS BEEN PERFORMED. ANSWER CHOICE: Only one possible answer X Several possible answers This is to warn you that wheels have been changed. Two wheels have just been installed on this vehicle. The driver responsible for tightening (re-torque) these two wheels before 100 km. You can't go on the road with this vehicle. Air pressure problem. Refer to if wrong answer:

