

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
> Business Class M2
> Cascadia
> 108SD/114SD

**Freightliner
Service Bulletin**

General Information

Vehicles built between June 1, 2011, and October 1, 2011, may have an alternate transmission interface connector installed due to a shortage from the supplier. See [Fig. 1](#) and [Fig. 2](#).




Fig. 1, Standard Transmission Interface Connector




Fig. 2, Alternate Transmission Interface Connector

The alternate connector is mapped 1-to-1 with the standard connector, and the wiring remains the same. Refer to [Table 1](#) for connector and terminal details.

Connector and Terminal		
Connector	Standard Connector	Alternate (Temporary) Connector
Connector	23-13153-056	23-13153-064
Terminal Pin	23-13211-021	23-13211-400

Table 1, Connector and Terminal

Warranty

This is an informational bulletin only. Warranty does not apply.