

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

Coronado
Business Class M2
> Cascadia
108SD/114SD

**Freightliner
Service Bulletin**

General Information

Cascadia daycabs with roof deflectors, built prior to April 2, 2012, may have a problem with the right-hand antenna hitting the roof deflector. See [Fig. 1](#). A thicker replacement antenna is available that resolves this problem. If the antenna is damaged by whipping against the roof deflector during vehicle operation, replace the antenna with part number PSO PFCPP504792.




Fig. 1, Antenna and Roof Deflector Proximity

Parts

| Replacement Antenna Part Number | |
|---------------------------------|-----------------|
| Part | Part Number |
| Multiband Antenna | PSO PFCPP504792 |

Table 1, Replacement Antenna Part Number

Warranty

This procedure is warrantable only if the antenna is damaged by the described condition and the repair is performed within the applicable base or extended coverage warranty period. If a failure is not found, this procedure is considered preventive and warranty does not apply.

Normal warranty applies. See [Table 2](#) for QuickClaim damage code and labor allowance information. Refer to this service bulletin by number at the beginning of the claim comments. See [Table 3](#) for OWL VMRS codes and labor allowance information. Enter this service bulletin number in the *Service Bulletin #*: field.

**Freightliner
Service Bulletin**

 FLA COE
 FLB COE
 FLD Conventional
 Business Class
 FLC 112 Conventional

 Century Class Conventional
 Argosy COE
 Cargo
 Columbia

 Coronado
 Business Class M2
 > Cascadia
 108SD/114SD

| QuickClaim Damage Code and Labor Allowance | | | |
|--|-----------|---------------------------|-------------|
| Damage Code | SRT Code | Description | Time: Hours |
| 746-000007130 | 753-5015A | Antenna, Cab Mounted, R/R | 0.2 |

Table 2, QuickClaim Damage Code and Labor Allowance

| OWL VMRS Codes and Labor Allowance | | | | | |
|------------------------------------|----------------|------------|-----------|---------------------------|-------------|
| Primary Failed Part | Component Code | Cause Code | SRT Code | Description | Time: Hours |
| Cab-Mounted Multiband Antenna | 052-003-005 | 12 | 753-5015A | Antenna, Cab Mounted, R/R | 0.2 |

Table 3, OWL VMRS Codes and Labor Allowance