

P0111

Fault code description

Humidity sensor - Abnormal rate of change

Possible cause

1. Liquid water droplet on sensor tip.
2. Voltage supply drop during start up

Additional information

Water condensation might affect sensor tip, which then instantly detects 100% RH.

Set condition of fault code

-

Reset condition of fault code

-

M028513 - 07/22/2015 19:15:46

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-12-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P0111, Diagnostic information

Technical data

["Sensor, humidity \(F852\)"](#)

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

["Humidity sensor \(F852\)"](#)

Block diagram

["PMCI-2"](#)

M046279 - 07/22/2015 19:14:37

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-12-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)