

P0219

Fault code description

Engine speed - Too high

Possible cause

1. Engine is overspeeding

Additional information

-

Set condition of fault code

This fault is set when the engine runs at 2300 rpm for one second.

Reset condition of fault code

This fault cannot be cleared from the ECU's memory. Contact the Engine Support Center for further instructions.

M028521 - 07/23/2015 03:14:25

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-12-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P0219, Diagnostic information

Technical data

["Sensor, crankshaft \(F552\)"](#)

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

["Crankshaft sensor \(F552\)"](#)

Block diagram

["PMCI-2"](#)

M046310 - 07/22/2015 18:01:46

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-12-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)