

P1715

Fault code description

Exhaust gas pressure after BPV - Data erratic, intermittent or incorrect

Possible cause

1. Faulty sensor

Additional information

-

Set condition of fault code

-

Reset condition of fault code

-

M028652 - 07/22/2015 18:10:02

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-14-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P1715, Diagnostic information

Technical data

["Sensor, pressure after BPV \(F823\)"](#)

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

["Pressure after BPV sensor \(F823\)"](#)

Block diagram

["PMCI-2"](#)

M046584 - 07/22/2015 19:06:49

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-14-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)