

P2106

Fault code description

Accelerator pedal - Limp home active

Possible cause

1. This is a cascading fault code. It is caused by other related fault codes.

Additional information

Do not troubleshoot this fault code. This is a cascading fault code which is caused by other related fault codes. Use DAVIE to find related fault codes and troubleshoot those.

Set condition of fault code

-

Reset condition of fault code

-

M028093 - 07/22/2015 15:03:44

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-15-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P2106, Diagnostic information

Technical data

Refer to the OEM service manual for more information.

Location of components

Refer to the OEM service manual for more information.

Electrical diagrams

["PMCI-2"](#)

Description of components

Refer to the OEM service manual for more information.

Block diagram

["PMCI-2"](#)

M046622 - 07/22/2015 17:07:21

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-15-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)