Resetting Erroneous Learned Roll Call ECUs on Vehicles with ICU4M

54-277

FLA COE	> Century Class Conventional	> Coronado	**Freightliner**
FLB COE	> Argosy COE	Business Class M2	**Service Bulletin**
FLD Conventional	Cargo	> Cascadia	
Business Class	> Columbia	108SD/114SD	
FLC 112 Conventional			

General Information

The ICU4M may learn roll call ECUs that are not present on the vehicle. When this happens, a roll call fault is shown on the ICU4M message center. These faults cannot be deleted unless the roll call ECU list is reset. Use the "rESEt EE" procedure described in this bulletin to eliminate roll call ECUs that are not installed on the vehicle.

Reset EE Procedure

1. Park the vehicle, set the parking brakes, and shut down the engine. Chock the tires.

2. Turn the ignition to ON without starting the engine.

3. Press the – button on the steering wheel several times until the SETUP INFORMATION message appears on the display.

4. Press My Info button one time.

5. Press the – button on the steering wheel several times until the display shows: PUSH → KEY TO RESET PARAMETERS.

6. Press the My Info button one time. The display will show "RESET PARAMETERS NO YES".

7. Press the + or – button on the steering wheel so that YES is highlighted.

8. Press the My Info button one time.

9. The ICU will now relearn all connected ECUs.

Warranty

This procedure is warrantable only if the described condition exists and the repair is performed within the applicable base or extended coverage warranty period. If a failure is not found, this procedure is considered preventive and warranty does not apply.

Normal warranty applies. See **Table 1** for QuickClaim damage code and labor allowance information. Refer to this service bulletin by number at the beginning of the claim comments. See **Table 2** for OWL VMRS codes and labor allowance information. Enter this service bulletin number in the *Service Bulletin #* field.

QuickClaim Damage Code and Labor Allowance			
Damage Code	**SRT Code**	**Description**	**Time: Hours**
732-000021590	732-5009A	ICU4M, Reset Parameters	0.3

Table 1, QuickClaim Damage Code and Labor Allowance

OWL VMRS Codes and Labor Allowance					
Primary Failed Part	**Component Code**	**Cause Code**	**SRT Code**	**Description**	**Time: Hours**
Software	F99-999-149	093	732-5009A	ICU4M, Reset Parameters	0.3

Table 2, OWL VMRS Codes and Labor Allowance