

P060A

Fault code description

PMCI-2 ECU - Internal error

Possible cause

1. Faulty ECU

Additional information

Reprogram the electronic unit PMCI-2 with the correct PRS file and clear the errors. Start the engine and let it idle to verify with DAVIE that the errors do not re-occur.

Set condition of fault code

-

Reset condition of fault code

-

M028555 - 07/23/2015 03:08:26

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P060A, Diagnostic information

Technical data

-

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

-

Block diagram

["PMCI-2"](#)

M046389 - 07/22/2015 16:06:10

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)