

P0A1F

Fault code description

ECU power supply - Voltage too low on ECU (D365)

Possible cause

1. Faulty wiring
2. Faulty connector
3. Faulty alternator

Additional information

-

Set condition of fault code

-

Reset condition of fault code

-

M028568 - 07/23/2015 03:05:57

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P0A1F, Diagnostic information

Technical data

["Power supply and earth of PMCI-2 electronic unit \(D365\)"](#)

Location of component(s)

Refer to the OEM service manual for more information.

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

Refer to the OEM service manual for more information.

Block diagram

["PMCI-2"](#)

M046412 - 07/22/2015 19:18:15

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)