12/15/2015 Rapido

P2227

Fault code description

ECU ambient pressure sensor - Abnormal rate of change on ECU (D365)

Possible cause

1. Faulty sensor

Additional information

-

Set condition of fault code

_

Reset condition of fault code

_

M028517 - 07/22/2015 19:15:07

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-15-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

12/15/2015 Rapido

P2227, Diagnostic information

Technical data

-

Location of component(s)

"Location information, PMCI-2"

Electrical diagram(s)

"PMCI-2"

Description of component(s)

"PMCI-2 electronic unit (D365)"

Block diagram

"PMCI-2"

Additional information

_

Set condition of fault code

-

Reset condition of fault code

This fault code will change to inactive immediately after the diagnostic runs and passes.

M046637 - 07/22/2015 18:15:39

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-15-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)