

P0503

Fault code description

Vehicle speed - Out of range

Possible cause

1. Faulty wiring
2. Faulty connector
3. Faulty sensor
4. Possible influence of external factors on the vehicle speed signal from speed sensor

Additional information

-

Set condition of fault code

Vehicle speed higher than 93.75 mph

Reset condition of fault code

This fault code will change to inactive immediately after the diagnostic runs and passes.

M028139 - 07/22/2015 17:12:28

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P0503, Diagnostic information

Technical data

Refer to the OEM service manual for more information.

Location of component(s)

Refer to the OEM service manual for more information.

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

Refer to the OEM service manual for more information.

Block diagram

["PMCI-2"](#)

M046371 - 07/22/2015 16:07:42

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)