

P140C

Fault code description

Crankcase air temperature - Voltage too low or short circuit to ground on ECU (D365) pin (C13)

This fault code is not used.

M028594 - 07/23/2015 03:04:34

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P140C, Diagnostic information

No diagnostic information available

M046497 - 07/22/2015 15:15:53

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)