

P1457

Fault code description

EGR temperature - Data valid but too high

Possible cause

1. Faulty EGR cooler
2. Fouled intercooler

Additional information

-

Set condition of fault code

-

Reset condition of fault code

-

M027650 - 07/22/2015 17:15:16

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P1457, Diagnostic information

Technical data

["Sensor, EGR temperature \(F749\)"](#)

Location of component(s)

["Location information, PMCI-2"](#)

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

["EGR temperature sensor \(F749\)"](#)

["EGR cooler"](#)

Block diagram

["PMCI-2"](#)

M046502 - 07/22/2015 15:15:27

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)