12/15/2015 Rapido

P252F

Fault code description

Engine oil level - Too high

Possible cause

- 1. Too much oil has been added
- 2. Leakage of other engine fluids into the oil sump (fuel, coolant)

Additional information

Oil level is checked with key on and engine not running.

Set condition of fault code

-

Reset condition of fault code

-

M028607 - 07/23/2015 03:03:35

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-15-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

12/15/2015 Rapido

P252F, Diagnostic information

Technical data

-

Location of component(s)

_

Electrical diagram(s)

-

Description of component(s)

_

Block diagram

"PMCI-2"

M046661 - 07/22/2015 16:08:50

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-15-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)