

P1360

Fault code description

CAN communication - Message (AT1GP) data error, Pressure 1 after Diesel Particulate Filter from aftertreatment system

Possible cause

- Check the system for fault codes regarding after-treatment and solve these first.

Additional information

-

Set condition of fault code

-

Reset condition of fault code

-

M028588 - 07/22/2015 18:13:25

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

P1360, Diagnostic information

Technical data

["CAN connections of PMCI-2 electronic unit \(D365\)"](#)

Location of component(s)

-

Electrical diagram(s)

["PMCI-2"](#)

Description of component(s)

-

Block diagram

["PMCI-2"](#)

M046491 - 07/22/2015 15:16:18

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)