12/13/2015 Rapido

P1495

Fault code description

Engine protection system - Power derate active



This fault is responsible for the actual derate of the engine.

Possible cause

1. This fault code is set by fault code P1496 (P1496 was active for 10 hours).

Additional information

_

Set condition of fault code

_

Reset condition of fault code

To solve this fault, fault P1496 must be solved.

This fault/derate can only be reset by DAVIE (with the EGR derate disable function)

M028283 - 07/22/2015 16:18:17

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)

12/13/2015 Rapido

P1495, Diagnostic information

Technical data

-

Location of component(s)

"Location information, PMCI-2"

Electrical diagram(s)

"PMCI-2"

Description of component(s)

_

Block diagram

"PMCI-2"

M046509 - 07/22/2015 15:14:52

This information applies exclusively to the entered chassis number or the selected engine type. Please take into account that this information may change daily. Therefore the provided information is only valid on 12-13-2015. You cannot derive any rights from the information provided with respect to vehicles and/or components of another series, with another chassis number, and/or of another date. (/)